Home Inspections by John

Confidential - Property Inspection Report - Confidential



, Wallace KS, 67761 Inspection prepared for: Inspection Date: 10/9/2010 Time: 0900 Size: 5200 Weather: sunny, 75 private treaty sale.

Inspector: John E. Zion
Kansas Registration # 0210-0128 Member ASHI
926 Paul St, Wray, CO, 80758
Phone: 970-630-1962
Email: johnzion@msn.com
www.zionhomeinspections.com



Executive Summary

Roof System/Compon	nents					
Page 12 Item: 7	Vent Pipe(s)roof penetrations	There is no apparent vents through roof, no sewer or vents, Furnace vents through sidewall. Chimneys have been removed				
Page 12 Item: 9	Roof Drainage System	• There is no gutter/downspout installed at the roof drainage system. Location: Potential water intrusion can occur and damage components. Recommend installing a gutter/downspout and properly extending away from the foundation to allow for proper drainage.				
Electrical System						
Page 21 Item: 5	Main Service Panel(s)	• The wiring within the main panel appears to have been done by a home handyman. This is not necessarily unsafe but other wiring should be checked to determine its conformity to safe electrical standards.				
Plumbing System						
Page 24 Item: 6	Water Heater(s) Condition	• SAFETY ISSUE: A Temperature Pressure Relief Valve (TPR Valve) present, but the valve discharge tube is missing. This safety valve releases water (and thus relieves pressure) if either the temp or pressure in the tank gets too high. The TPR valve discharge tube must be made of copper, iron, or CPVC (NOT regular PVC). It must terminate within 6" above the floorthe end cannot be threaded or have a fitting.				
Kitchen, Breakfast No	ook, & Appliances					
Page 25 Item: 2	Sink / faucet / disposal	• sink has an "S" trap, no proper vent, if this causes sewer odor problems I would suggest installing air admittance valves.				
Bath Room #1	·					
Page 32 Item: 9	Fixtures / GFCI Receptacles	• Safety Issue: While GFCI's may not be required in this home because of it's age, you should consider installing GFCI's in any bathroom receptacle for the safety of yourself, family, and guests.				
music room east						
Page 36 Item: 3	Doors / Windows	door will not latch properly, missing latch				
Clamity Jane bedroom						
Page 39 Item: 6	Smoke Alarm	Safety Issue: Smoke alarms should be installed inside each sleeping room / bedroom.				

Inspection/Site Details

1. Inspection Time

Start: 09:00 AM End: 12:30 PM

2. Attending Inspection

- Client present
- Seller present
- Fully Participated

3. Residence Type/Style

- · Single Family Home
- Colonial

4. Year Built

age/year 1880, addition 1909

5. Square Footage

sq. ft. 5200

6. Lot Size

lot sq. ft. 4 acres

7. # of Bedrooms

bedroom/s 6 bedroom

- 2 finished bedroom on main floor---
- 2 finished bedroom on 2nd floor---
- 2 unfinished bedroom on 2nd floor---
- 3 posable unfinished bedroom in unfinished basement.

8. Bathrooms

3 bathroom--2 finished, 1 unfinished

9. Direction Of Front Entrance

For the purpose of this report the building is considered to be facing, South

10. Occupancy

- Vacant
- Access to some items such as: electrical outlets/receptacles, windows, wall/floor surfaces, and cabinet interiors may be restricted by furniture or personal belongings. Any such items are excluded from this inspection report.
- The water utilities were off at the time of inspection.

11. Weather Conditions

Clear, sunny sky

70 degrees

Exterior Surfaces

1. House Covering/Siding

Satisfa ctory	Margin al	Poor	Safety issue	N/A
	Х			

Materials: Composition Board • Wood Plank

Observations:

• There are areas of the siding that ares loose/damaged/warped. Water can infiltrate & damage the framing. Recommend repairing any loose or damaged areas. Priming, caulking painting, and some trim repair is needed





Exterior Surfaces House Covering/Siding

Exterior Surfaces House Covering/Siding

2. Eaves, Soffits and Fascia

Satisfa ctory	Margin al	Poor	Safety issue	N/A
	Х			

Materials:

Wood

Observations:

- Recommend attaching, prepping, priming and painting any exposed wood trim
 Warping
 Broken areas

- bird nests



Exterior Surfaces Eaves, Soffits and Fascia



Exterior Surfaces Eaves, Soffits and Fascia





Exterior Surfaces Eaves, Soffits and Fascia

Exterior Surfaces Eaves, Soffits and Fascia

3. Exterior Glass

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

- Materials:


 Single glazed windows

 single glazed windows with storm windows

 Observations:

 Exterior glass in satisfactory condition, meaning it is repairable and should have storm windows installed.

 Window glazing needs repair or replacement



typical windows with storms



cracked glass



typical repair needed

4. Exterior Doors

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Χ				

Materials: Solid Wood • Metal covered wood door

Observations:

- The front entry is in satisfactory condition
 the front entry storm door is functional
 back door is in satisfactory condition
 back storm door is serviceable

- weathered
- deteriorated materials







Exterior Surfaces Exterior Doors





kitchen entry

with ramp





outside basement

replace entry

5. Window/Door Frames and Trim

Satisfa ctory	Margin al	Poor	Safety issue	N/A
	X			

Materials: Wood

Observations:
• Exposed wood surfaces observed. Wood rot & deterioration can occur. Prep, prime and paint wood trim surface where paint is peeling or missing.



typical window

6. Exterior Caulking

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observations:
	Χ				Caulking is recommended around windows/doors/masonry ledges/corners/utility penetrations.

7. Exterior Vents (excluding roof vents)





furnace vent range hood

8. Exterior Faucets

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Description: frost free yard hydrant
					Observations:
					 Operated properly when tested, water shut off



Exterior Surfaces Exterior Faucets

Grounds

Observa	I. VVa	I. Walkways								
Observa			Poor		N/A	Materials				
	X					Observat • Appeared fund				

: Concrete tions:

ctional and satisfactory.

2. Driveways

1 Wallawaya

ctory	iviargin al	Poor	issue	N/A	Materials: Dirt

3. Grading and Drainage

Satisf ctory	Margin al	Poor	Safety issue	N/A
	Χ			

- Observations:

 Drainage away from the home foundation should be 6 to 8 inches below wood or composition siding and slope away from home at the rate of 1" per foot for 6'.

 Drainage is generally away from home

 some low spots need filled and graded.



this corner needs drainage improved

4. Window Wells

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Materials: Cement
X					Observations:

• The window well covers are damaged. Recommend removing or replacing





needs cover replaced

cover



Grounds Window Wells

5. Vegetation Affecting Structure

Satisfa Margin Poor Safety N/A Description: Trees Observations:

Vegetation should be trim

• Vegetation should be trimed away from the home to maintain a clearance of 12 to 18". This will allow the siding to remain dry, prevent damage from tree limbs, prevent insect damage and prevent mold and mildew growth.



remove tree, or trim away from house

6. Front Stoop/Steps

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Χ				

Materials: Concrete Observations:

· Entry stoop and steps are satisfactory, in good repair





Grounds Front Stoop/Steps

Grounds Front Stoop/Steps

Roof System/Components

1. Style/Pitch

House: Combination

with dormers

Steep slope: roof angle (pitch) more than 45 degrees

2. Method of Roof Inspection

Observations: Walked on Roof Surface

3. Roof Covering Type

House: Fiberglass-based asphalt shingles • Metal

4. Age of Roof Covering


House:
• five to ten years

5. House Roof Condition

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Χ				

Observations:
• These shingles appear to be in the first third of their life cycle.





from widows walk



asphalt shingles



soldered tin front entry roof

tin roof

6. Flashings and Valleys

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

Materials: Shingles- closed valley

Observations:
• Appeared functional, at time of inspection





trap from widows walk

widows walk



front walk way

7. Vent Pipe(s)roof penetrations

Satisfa Margin Poor Safety N / A issue

Observations:

• There is no apparent vents through roof, no sewer or vents, Furnace vents through sidewall. Chimneys have been removed

8. Chimney(s)

Satisfa Margin Poor Safety N / A issue

Observations:

• Masonry chimneys have been removed. There were three

9. Roof Drainage System

Satisfa Margin Poor Safety N / A issue

Observations:

• There is no gutter/downspout installed at the roof drainage system. Location: Potential water intrusion can occur and damage components. Recommend installing a gutter/downspout and properly extending away from the foundation to allow for proper drainage.

Foundation and Structure

1. Ceiling and Roof Structure

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

- Description:
 Roof framing system:
 Rafters
 1x solid plank sheathing

Observations:

• The rafter and ceiling system appears to be properly designed for this structure.

2. Foundation Type

- Description:

 Combination Basement and Crawlspace

 Post and girders system for center support wall

3. Foundation Walls

Satisfa ctory	Margin al	Poor	Safety issue	N/A
X				

Description: Stone / Native rock

Observations:

The visible portion of the foundation walls appear to present no problem





mortar crack, possible leak to interior

native rock



native rock

4. Wall Structure

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Description:
Х					 2x4 construction Observations

Observations:
• The wall structure showed no apparent problems





Foundation and Structure Wall Structure

note support beams



Foundation and Structure Wall Structure

5. Foundation Floor

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Description: concrete
Х					Observations: • Visible areas appear satisfactory

6. Floor Structure

ctory	al	FUUI	issue	IN/A	Description: Dimensional lumber wood Joists
Χ					Observations: • Visible areas appear satisfactory at the time of inspection.

7. Crawl Space

Satisfa ctory	Margin al	Poor	Safety issue	N/A



Foundation and Structure Crawl Space

Note that minor settlement or "hairline" cracks in garage or basement slabs are not noted in an inspection, as they are normal to properties of any age. They should, however, be monitored for expansion and sealed as necessary. Residential inspections only include garages and carports that are physically attached to the house. They are not considered habitable, and conditions are reported accordingly.

Inspectors are not required to enter any crawlspace areas that are not readily accessible, less than 36" clearance, wet (electrical shock hazard), or where entry could cause damage or pose a hazard to the inspector.

We recommend that all attic hatches have a batt of fiberglass insulation installed over them, and that the hatch be sealed shut with latex caulk. This will keep warm moist air from entering the attic, which may cause condensation or even mold. Note that *every* attic has mold; mold is everywhere. Some attics have some minor *visible* mold. This is often a result of the building process, when materials get wet during construction. If there is *extensive* mold, or mold that appears to have grown due to poor maintenance conditions, we will report it to you, the client. If the hatch is sealed shut when we go to inspect the attic, it can only be unsealed by the owner or their representative, as our insurance prohibits us from performing any destructive testing or entry. In accordance with industry and insurance standards, we will not attempt to enter an attic that has no permanently installed steps or pull-down stairs; less than thirty-six inches of headroom; does not have a standard floor designed for normal walking; walking, in the inspector's opinion, may compromise the ceiling below; is restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we will inspect the attic as best we can from the access point, with no comments or evaluations of areas not readily viewed from the hatch area.

Attic

1. Method of Inspection

Method:

Viewed From Hatch - Attic area too short to to walk in

Inspectors will not crawl the attic area when they believe it is a danger to them or that they might damage the attic insulation or framing. This is a limited review of the attic area viewed from the hatch only.

2. Access Type/Location

Satisfa ctory	Margin al	Poor	Safety issue	N/A
X				

Observations:

2 shuttles

Located in:

Bedroom Hall and bedroom





Jane bedroom

hall

3. Insulation

Satisfa Margin Poor Safety N / A issue

Materials: Fiberglass, batts
Depth/R-Value:
• six inches equal R-18

Observations: Visible insulation is satisfactory





Attic Insulation

Attic Insulation





attic #2

need to install missing insulation

4. Attic vapor barrier

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

Observations:

• Vapor barrier is in satisfactory condition

5. Roof Ventilation

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

Description:

• Gable louver vents, only one.

Observations:

Attic ventilation is marginal



Attic Roof Ventilation

6. Vent(s) Piping Through Attic

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observations
Х					• no vents through atti

Heating, Ventilation and Air Conditioning System(s)

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

4	_					/ \
-	П	her	m	റവ	トヘナ	/cl
	,	121	1111		111	
		101	,,,,	,,,	uı	9,

ctory	Margin al	Poor	issue	N/A
Χ				

Observations:

Functional at the time of inspection. Owners present indicated that the heating and cooling systems were fully functional.

2. Primary Heating

Satisfa ctory	Margin al	Poor	Safety issue	N/A	
Х					

Description:

- Mid Efficiency type furnace--over 80% efficient. See Limitations.
- forced air gas furnace
- Location: Basement utility furnace room

Observations:

• No deficiencies were observed, at time of inspection.



Heating, Ventilation and Air Conditioning System(s) Primary Heating



Heating, Ventilation and Air Conditioning System(s) Primary Heating

3. Electric Safety Switch

Location: Within sight of furnace unit

4. Age of Furnace/Air Handler

Age

5. Gas Meter

ctory	Margin al	Poor	issue	N/A	Observations
Χ					• on site propane tank



propane tank

6. Fuel Cutoff

Location:

- Shut off valve locations
- Furnace

7. Heat Distribution

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Description: Galvanized sheetmetal ductwork
X					Observations:
					 Appeared functional, at time of inspection.

8. Filter(s)

ctory	al	1 001	issue	14771	D
	Χ				• p
					, ,,

Description: pleated air filter

- 16x20x1

Observations:

• The furnace filter is dirty. Filters help clean the house air, making the environment more pleasant. Filters also clean the air before it passes through the blower and heat exchanger. This helps to keep these furnace components working efficiently. It is recommended to change the filter and then regular inspection & maintenance is advised.



Heating, Ventilation and Air Conditioning System(s) Filter(s)

_	_			_		
n	n.	rin	nar			linc
9	PΙ	ш	и	vı.	<i>()()(</i>	ш

Satisfa ctory	Margin al	Poor	Safety issue	N / .
Х				

Description:

Air Cooled Central Air Conditioner

Observations:

• Appeared functional at the time of inspection. Owner indicated A/C was fully functional.



Heating, Ventilation and Air Conditioning System(s) Primary Cooling

10. Energy Source

Energy: Electric

11. Age of Outside Compressor Unit(s) / Heat Pump(s)

Age:

Fireplaces/Wood Stoves

Electrical System

1. Service Entry

ctory	al	FUUI	issue	IN / A
Х				

Service Drop Type: Underground service lateral Observations:

Appeared functional and serviceable, at time of inspection.

2. Meter Location

utility pole • East

3. Electrical Service Rating

200 amps

4. Service Entry Conductors

ctory	Margin	Poor	issue	N/A
Х				

Description: Copper

Observations:

· Appeared serviceable, at time of inspection.

5. Main Service Panel(s)

Satisfa ctory	Margin al	Poor	Safety issue	N/A
	Х			

Description: Manufacturer: • Square D • entrance hall Observations:

- see comment page and photos
 The wiring within the main panel appears to have been done by a home handyman. This is not necessarily unsafe but other wiring should be checked to determine its conformity to safe electrical standards.





Electrical System Main Service Panel(s)

missing strain relief



knockouts missing, safety issue

6. Main Disconnect

Satisfa ctory Margin al Safety issue

Location: meter pole 100 amp breaker • Inside main panel 200 amp breaker

Observations:

• 200 amp 240 main service panel



note breaker below meter

7. Service Grounding/Bonding

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Description: Ground Connection Not Visible
	Х				Observations: • Ground wire connection could not be located due to finished walls

8. Sub Panel(s)

ctory	al	1 001	issue	IN/A	Description: Location: • Basement • attic, see comment / photo
					Observations:
					• Sub panels located in basement for water heater and lights. one panel located in attic beside hatch, see comment page





basement, needs cover installed

in attic #2, Install cover

9. Wiring Method branch circuits

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Materials: Wiring type: non-metallic sheathed cable "Romex"
	Х				Observations: • Amateur wiring in evidence
					 Visible wiring appeared functional, at time of inspection.



missing strain relief

10. Switches, Receptacles, Lights

Satisfa ctory	Margin al	Poor	Safety issue	N/A	
X					

Description: Grounded Observations:

• A representative number of receptacles, switches and lights were tested and are generally serviceable, unless otherwise noted.

Plumbing System

1. Water Supply Source

The water is supplied by the municipal system.

2. Service Piping Into The House

Materials: Copper

3. Main Water Shut Off

Satisfa ctory	Margin al	Poor	Safety issue	N/A
	X			

Location: Meter well is located in front of and east of the home, outside fence.

Observations:

• The main shut off valve for the water supply was not found. Consult the seller regarding the location or existence of a main shut off valve.



meter well

Home Inspections by John

4. Service and Branch Pip	INA

Satista	Margin al	Poor	Safety	N/A
Χ				

Materials: Copper • Galvanized • Thermoplastic - CPVC (Chlorinated Polyvinyl Chloride) - yellowish white in color Observations:

• No Deficiencies Observed at the Visible Portions of the Supply Piping.

5. Water Heater(s)

Description:

- US Craft master
- · Location: basement utility room

Capacity:

• 50 Gallons

6. Water Heater(s) Condition

ctory	Margin	Poor	issue	N/A
			Х	

Age:

• 8 Years -- built: Jan 2000

Observations:

• SAFETY ISSUE: A Temperature Pressure Relief Valve (TPR Valve) present, but the valve discharge tube is missing. This safety valve releases water (and thus relieves pressure) if either the temp or pressure in the tank gets too high. The TPR valve discharge tube must be made of copper, iron, or CPVC (NOT regular PVC). It must terminate within 6" above the floor--the end cannot be threaded or have a fitting.



missing relief pipe

7. Interior Gas Supply Piping

ctory	Margin	Poor	issue	N/A
Х				

Materials: Black Iron • Corrugated Stainless Steel Tubing (CSST)

Observations:

• No deficiencies observed at the Visible portions of the gas supply piping.

8. Waste System and Piping

Description: Private sewage disposal - Septic - system

9. Drain, Waste & Vent Piping

Satisfa ctory	Margin al	Poor	Safety issue	N/A
X				

Materials:

- Cast Iron
- Thermoplastic PVC (Polyvinyl Chloride) normally white in color

Observations:

• Visible piping appeared serviceable at time of inspection.



crawl space

Kitchen, Breakfast Nook, & Appliances

1. Cabinets / Countertops

Satista	Margin al	Poor	Safety	N/A	C
V					• (
X					• (

Observations:


- Cabinets are in satisfactory condition Countertops are in satisfactory condition

2. Sink / faucet / disposal

ctory	al	PUUI	issue	IN / A
X		Χ		

Observations:

- Sink is in satisfactory condition
 faucet is in satisfactory condition
 sink has an "S" trap, no proper vent, if this causes sewer odor problems I would suggest installing air admittance valves.



sink area

3. Fixtures / GFCI

Satisfa ctory	Margin al	Poor	Safety issue	N/A
Х				

Observations:

- GFCI tested and operated correctly Kitchen lights are satisfactory

	_								
4	D.	IS	h	M	'n	ςl	h	ρ	r

ctory	al	1 001	issue	14771
Χ				

Observations:

• Dishwasher was not tested, commercial unit.

5. Range / oven / cook top

ctory	al	Poor	issue	N/A
Х				

Observations:

• Suggest you operate all appliances before closing



Commercial kitchen

6. Range Hood

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observatio
Χ					• vents to exterior

ns:

7. Heat Source

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observations:
Χ					Heat source is satisfactory

Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Walls and ceilings


Satisfa ctory	Margin al	Poor	Safety issue	N/A





grand entry

grand entry



upper landing

Garage

Dining room

1. Walls / Ceilings

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observations:
Х					 Satisfactory





tea room tea room

2. Floors

Satisfa Margin ctory al Safety issue N/A

Observations: • Satisfactory



Dining room Floors

3. Doors / Windows

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Ol
X					• D

bservations:

oor was not operated due to furniture

4. Lights, Recptacles

Satisfa ctory	Margin al	Poor	Safety issue	N/A
X				

Observations:

• random sample of receptacle/s indicated proper operation

5. Heat Source

ctory	al	 issue	
Х			

Observations:

Satisfactory

Living Room

1. Walls / Ceilings

Satisfa ctory	Margin al	Poor	Safety issue	N/A





main floor bedroom

servant quarters



servant quarters

Family Room

1. Wall / Ceiling

Satisfa ctory	Margin al	Poor	Safety issue	N/A	



Parlor / dining area

Parlor / dining area





music room

music room

Master bathroom

Master Bedroom

Bath Room #1

1. Location

Location:
• Main Bathroom

2. Walls / Ceiling

Observations:
• Walls and ceilings should be water resistant materials



main floor bathroom

3. Floor				
	Observations: • Satisfactory			
4. Vanity / Basin				
	Observations: • one basin			
5. Tub / Shower				
	Observations: • tub only • Tub in satisfactory condition			
6. Toilet				
	Observations: • toilet is in satisfactory condition			
7. Exhaust Fan				
	Observations: • no vent			
8. Plumbing				
	Observations: • Satisfactory			
9. Fixtures / GFCI Receptacles				
Satisfa Margin Poor Safety N/A issue	Observations: • Safety Issue: While GFCI's may not be required in this home because of it's age, you should consider installing GFCI's in any bathroom receptacle for the safety of yourself, family, and guests.			

10. Door / Windows

Satisfa ctory	Margin al	Poor	Safety issue	N/A	Observations:
Χ					 door operates properly

Bed Room Master

1. Wall / Ceiling

Satisfa ctory	Margin al	Poor	Safety issue	N/A





bridal suite



bridal suite



bridal suite

bridal suite



unfinished bedroom upper

unfinished bedroom



bedroom calamity Jane



Calamity Jane room

Laundry Room

Misc Comments & Observations

1. Misc Information

Materials:

- The standards that I use to rate the different components of the house reflect a house built in 1880 not a modern home. For example a door in your old home might be satisfactory because it is repairable while in a new home it might need replaced.
- The water was turned off to this home at the time of the inspection so there is the possibility that minor repairs might need
- done to the fresh water or the waste water system. I would suggest haveing the water turned on before closing.

 The outside basement entry is not a sound structure. I would suggest either a total new replacement entry way or you might consider closing the basement doorway and completely doing away with the outside entry. You might consider installing a new egress / exit window where the current doorway is.
- Electrical: The breaker on the meter pole is 100 amp and the main breaker in the house is a 200 amp. Normally the higher rated 200 amp breaker would be on the meter box breaker. The main breaker box in the kitchen area should have some strain relief clamps to protect the wire from the sharp edges on the breaker box and the inside cover should be replaced because of the breaker knockouts missing creates a safety issue. The sub panel in the attic should have been installed in a hallway where there would have been easier to access and where it could be easy to find. The sub panel in the attic and the one in the basement should have the covers installed.
- Plumbing: The waste system is not vented to the outside. The vent system if installed correctly allows air to enter the waste system to equalize pressure and lets toilets flush better and stops sewer gas from entering the home. This problem can be partly solved with the installation of Air admittance Valves, however even then you should have at least one vent to the outside. This problem will be noticed from sinks, toilets, etc bubbling when draining.

Bedroom / bathroom unit

residents living and dining area

Office area

beauty shop

Employee lounge

Kitchen Facility

bedroom 1 main floor

Bed Room #3

Bed Room #4

Bath Room #2

Bath Room #3

Rec Room

parlor, dining area west side 1. Walls / Ceilings Satisfa Margin ctory al Observations: Satisfactory 2. Floors Satisfa Margin ctory al Safety Observations: issue Satisfactory 3. Doors / Windows Satisfa Margin ctory al Safety issue Observations: Satisfactory 4. Lights, Recptacles Satisfa Margin Poor ctory al Safety issue Observations: • random sample of receptacle/s indicated proper operation 5. Heat Source Satisfa Margin ctory al Safety issue N/A Observations: Satisfactory grand entry 1. Walls / Ceilings Satisfa ctory Margin Observations: • walls and ceilings are in satisfactory condition 2. Floor Satisfa Margin Poor Safety N/A Observations: issue • floor is in satisfactory condition 3. Door / Windows Satisfa Margin ctory al N/AObservations: door operates properly 4. Lights / Receptacles Satisfa Margin ctory al Safety issue Observations: • A representative number of switches and receptacles were checked for proper operation 5. Heat Source Satisfa Margin ctory al Safety issue N/AObservations: Satisfactory

Satisfa Margin

ctory

Poor

Safety issue

N/A

Observations:

Satisfactory

music room east 1. Walls / Ceilings Satisfa Margin Poor ctory al Safety issue N/A Observations: Satisfactory 2. Floors Satisfa Margin ctory al Safety issue N/AObservations: Satisfactory 3. Doors / Windows Satisfa Margin Poor ctory al Safety N/AObservations: Satisfactory door will not latch properly, missing latch 4. Lights, Recptacles Satisfa Margin Poor ctory al Safety issue Observations: • random sample of receptacle/s indicated proper operation Lights and light fixtures operated properly bedroom 1 main floor tea room 1. Walls / Ceilings Satisfa Margin ctory al Safety issue N/AObservations: walls and ceilings are in satisfactory condition 2. Floor Satisfa Margin ctory al Safety issue N/A Observations: · floor is in satisfactory condition 3. Door / Windows Satisfa ctory Margin Safety Observations: Window operates properly door operates properly 4. Lights / Receptacles Satisfa Margin ctory al Safety issue N/AObservations: • A representative number of switches and receptacles were checked for proper operation 5. Heat Source

Bridal sweet upper floor 1. Bed Room Location Location Second floor bedroom #1 2. Wall / Ceiling Satisfa Margin Poor Safety issue N/A Observations: · walls and ceilings in good repair 3. Floor Satisfa Margin ctory al Safety issue N/AObservations: floor shows no serious defects 4. Lights / Receptacle Satisfa Margin ctory al Safety issue N/AObservations: • a representative number of receptacles and all switches were tested for proper operation 5. Door / Windows Satisfa Margin ctory al Safety issue Observations: Satisfactory 6. Smoke Alarm Satisfa Margin Safety issue N/A Observations: ctory Safety Issue: Smoke alarms should be installed inside each sleeping room / bedroom. bridal sweet bathroom 1. Location Location: · Bathroom, 2nd floor 2. Walls / Ceiling Satisfa Margin ctory al Safety N/AObservations: Satisfactory 3. Floor Satisfa Margin Poor Safety N/AObservations: Carpet flooring 4. Vanity / Basin Safety issue Satisfa Margin ctory al N/AObservations:

one basin

5. Tub / Shower	
Satisfa Margin Poor Safety N/A ctory al issue Observations:	
tub only Tub in satisfactory condition	
Tub in satisfactory containon	
6. Toilet	
Satisfa Margin Poor Safety N/A ctory al Sasue Observations:	
toilet is in satisfactory condition	
7. Exhaust Fan	
Satisfa Margin Poor Safety N/A issue Observations: • window in lieu of vent	
× Wildow III lied of Verit	
9 Dlumbing	
8. Plumbing Satisfa Margin Poor Safety N/A Observations	
ctory al issue Observations: • Satisfactory	
X	
9. Fixtures / GFCI Receptacles	
Satisfa Margin Poor Safety N/A ctory al issue Observations:	
• Safety Issue: While GFCI's may not be required in this home because of it's age, you should c	onsider installing GFCI's in any
bathroom receptacle for the safety of your self, family, and guests.	
10. Door / Windows	
Satisfa Margin Poor Safety N/A ctory al issue Observations:	
window operates properly door operates properly	
11. Heat Source	
Satisfa Margin Poor Safety N/A Observations:	
• Satisfactory	
upper landing	
1. Walls / Ceilings	
Satisfa Margin Poor Safety N/A ctory al issue Observations:	
walls and ceilings are in satisfactory condition	
2 Floor	
2. Floor Satisfa Margin Poor Safety N/A	
ctory al issue Observations: • floor is in satisfactory condition	
X III Satisfactory condition	
3. Door / Windows	
Satisfa Margin Door Safety N / A	
Ctory al issue Observations: • Window operates properly	
X William operates property	

4. Lights / Receptacles	
Satisfa Margin Poor Safety N / A ctory al issue	Observations:
X	A representative number of switches and receptacles were checked for proper operation
	bedroom upper, s/w corner unfinished
1. Bed Room Location	
I. DEU KUUIII LUCAUUII	
	Location • Second floor bedroom #2
	555514 1001 2541 5511
2. Wall / Ceiling	
Satisfa Margin Poor Safety N / A ctory al issue	Observations:
X	Satisfactory, this room is unfinished, there is no apparent problem with on going construction
	Clamity Jane bedroom
1. Bed Room Location	
	Location
	Second floor bedroom #3
2. Wall / Ceiling	
Satisfa Margin Poor Safety N / A	Observations:
ctory al issue	• walls and ceilings in good repair
X	
3. Floor	
Satisfa Margin Poor Safety N / A ctory al issue	Observations:
Citity at issue	• floor shows no serious defects
4. Lights / Receptacle	
Satisfa Margin Poor Safety N / A ctory al issue	Observations:
	• a representative number of receptacles and all switches were tested for proper operation
X	
5. Door / Windows	
Satisfa Margin Poor Safety N / A	Observations
ctory al issue	Observations: • door is in good working order
X	door is in good working order Window is in good working order
6. Smoke Alarm	
Satisfa Margin Poor Safety N / A	Observations
ctory al issue	Observations: - Safety Issue: Smoke alarms should be installed inside each sleeping room / bedroom.
X	, and the second control of the second contr
7. Heat Source	
Satisfa Margin Poor Safety N / A	
	Observations: • Satisfactory
X	